

TECHNICAL NOTICE


BURNER MANIFOLD SEALING GASKETS

In a move to improve combustion equipment reliability BH-F will supply new viton gaskets in place of fibre washers on all new orders.

The fibre washer used to seal the burner pipe onto the burner manifold has sometimes failed to reseal when the manifold position is adjusted at the end of the forehearth warm-up.

The new viton material has been tested to ensure that, even after exposure to high temperatures, the gasket reseals successfully. During these tests it was found that much less clamping force is required to achieve a good seal.

Fibre washer



New Gasket.

